

NEW TO RANGE




Guide Pin Kit for Knorr* Brake Calipers

Part Number WA256

Guide pin manufactured from 303 Stainless

Replaces all other designs



Part of the Intelligent Braking
Range of Products

Over 70% of caliper failures are due to worn or damaged guide pins.

Poor caliper movement is a major cause of premature friction wear and rotor heat damage.

Thos. Winnard & Sons Ltd

Mangham Road Rotherham South Yorkshire England S62 6EF
Telephone Export Sales +44 (0)1709 712002 Fax +44 (0)1709 712001
Email sales@winnard.co.uk www.winnard.co.uk

*Manufacturers part numbers and names are used for reference purposes only. Contact sales for pricing information
Copyright Thos. Winnard & Sons Ltd 2010